

ACE Golden Rules

PPE

Hard Hat



Worn correctly, not backwards, no hats or beanies.

Safety Glasses



Must conform to Australian Standards. Double eye protection required for grinders & demo saw operations

Safety Footwear



Steel capped boots

Clothing



Long sleeve, high vis shirt

Gloves



Worn or carry on clip at all times

Sun Smart



Wear sunscreen, use brims for hard hats

Plant & Equipment

Authorisation



Only licensed & competent persons to operate plant

Maintenance



All plant faults to be reported.

Safety



Never approach working equipment from blind spots

Operations

Trenching Entry



Entry to trenches 1.5m or greater require shoring. No working outside shoring

Electrocution Hazard



3-6.4m require spotter- 3 meters or less NO GO Zone (Restrictions apply above or below ground)

SWMS



SWMS must be signed & followed as documented

Fatigue Management



10 hour breaks between shifts must be applied

Incidents



All incidents & near misses must be reported to the site supervisor

Spotters



Spotters required when working in vicinity of overhead or underground infrastructure

Permit



Breaking ground prohibited without completed excavation permit.

Working at Heights



When working at 2 meters or greater fall protection must be used

Fitness for Work

Drugs & Alcohol



Consumption, impairment, possession or sale of illicit drugs is strictly prohibited